




STEP by STEP INSTALLATION GUIDE



GAMDIAS

KRATOS IP2 750G

90% EFFICIENCY POWER SUPPLY

GAMDIAS

KRATOS IP2 850G

90% EFFICIENCY POWER SUPPLY

GAMDIAS

KRATOS IP2 1000G

90% EFFICIENCY POWER SUPPLY

GAMDIAS

KRATOS IP2 1200G

90% EFFICIENCY POWER SUPPLY

Package Contents

Model Name	KRATOS P2-750G				
AC Input	100-240V~ , 11-5.5A , 47-63 Hz				
DC Output	+3.3V	+5V	+12V	-12V	+5Vsb
Max. Output Current	20A	20A	62.5A	0.3A	3A
Max. Output Power	130W		750W	3.6W	15W
Total Power	750W				

Model Name	KRATOS P2-850G				
AC Input	100-240V~ , 11-5.5A , 47-63 Hz				
DC Output	+3.3V	+5V	+12V	-12V	+5Vsb
Max. Output Current	20A	20A	70.5A	0.3A	3A
Max. Output Power	130W		846W	3.6W	15W
Total Power	850W				

Model Name	KRATOS P2-1000G				
AC Input	100-240V~ , 13-6.5A , 47-63 Hz				
DC Output	+3.3V	+5V	+12V	-12V	+5Vsb
Max. Output Current	20A	20A	83A	0.3A	3A
Max. Output Power	130W		996W	3.6W	15W
Total Power	1000W				


Model Name	KRATOS P2-1200G				
AC Input	100-240V~ , 15-7A , 47-63 Hz				
DC Output	+3.3V	+5V	+12V	-12V	+5Vsb
Max. Output Current	20A	20A	100A	0.3A	3A
Max. Output Power	130W		1200W	3.6W	15W
Total Power	1200W				



The power supply should be powered by the source indicated on the rating label

Package Contents

A



X1

B




X4


Package Contents

KRATOS P2-750G
KRATOS P2-850G


MOTHERBOARD POWER CABLE



SATA CABLE




CPU EPS CABLE
600mm




MOLEX CABLE
500mm




GPU PCI-E CABLE
500mm



RGB SYNC
500mm




12VHPWR CABLE
600mm




Package Contents

KRATOS P2-1000G
KRATOS P2-1200G


MOTHERBOARD POWER CABLE




SATA CABLE




CPU EPS CABLE
600mm




MOLEX CABLE
500mm




GPU PCI-E CABLE
500mm



RGB SYNC
500mm




12VHPWR CABLE
600mm




Connector Interface


KRATOS P2-750G




KRATOS P2-850G




KRATOS P2-1000G




KRATOS P2-1200G



- 1** Turn off the PSU before installing by pushing I/O switch to "O" position.




2




3 Motherboard

A



4 CPU




A

5

PCIE


A




6

SATA


A



7 Molex




8 RGB SYNC



9

Plug in the AC power cord.



10

Turn on the PSU after installing by pushing I/O switch to "I" position.

