




IceSLEET™ X5

Quick Start Guide

Iceberg-Thermal.com

Box Content

A



x 1

B



x 4

C



x 1

AMD

D




x 4

E



x 4

F



x 2


INTEL

G



x 4

H




x 2

I



x 4

J



x 1


AMD

AM4


B



F



D




AM3(+) / AM2(+) / FM2(+) / FM1


B



F




E




AMD


AM4



AM3(+) / AM2(+) / FM2(+) / FM1





AMD





INTEL

LGA 2066 / 2011-0 / 2011-3 (Square ILM)


B**H****G**

LGA 1200 / 115X / 1366 / 775


B**H****I****J**

INTEL

H




J




INTEL

LGA 2066 / 2011-0 / 2011-3 (Square ILM)




INTEL

LGA 1200 / 115X / 1366 / 775




INTEL


LGA 1200 / 115X / 1366 / 775




Step 1




Step 2




Step 3




Step 4




Step 5



Step 6



Step 7



Step 8

